

sphere & sphere big







sphere 1













white / white painted black / white painted

T46H1IWL T46H1IZL

sphere 3











white / white painted black / white painted

T46H2IWL T46H2IZL

sphere 7














T46H3IWL T46H3IZL

sphere big 1











white / white painted black / white painted

T46H4IZL T46H4IWL

sphere big 3











white / white painted black / white painted

T46H5IWL T46H5IZL

sphere 7 big











white / white painted black / white painted

T46H6IWL T46H6IZL

INSTALLATION SHEET


PROJECT NAME:

SUSPENDING THE SPHERE

SUSPEND THE SPHERE AND ADJUST AS REQUIRED.

WIRING AND CANOPY INSTALLATION

- A- ADJUST THE POWER CABLE LENGTH TO POSITION. CUT THE CABLE SURPLUS.
- B- RAISE THE CROSSBAR AGAINST THE CEILING AND FASTEN TO THE JUNCTION BOX USING (2) MOUNTING SCREWS.
- C- MAKE ALL NECESSARY CONNECTIONS (FOLLOWING WIRING DIAGRAM AND POLARITY MARKING) USING THE TWIST CONNECTORS (NOT INCLUDED). MAKE THE CONNECTION FIRST AND INSTALL THE CROSSBAR AFTER.
- D- PLACE THE CANOPY OVER THE CROSSBAR AND SECURE ASSEMBLY IN PLACE WITH (2) SCREWS.



General installation and maintenance directives concerning factory guarantee. Connecting and testing the lamps must always happen by an acknowledged electrician according to the locally applying regulations on electric installations. Do not place on a flammable surface.



SHEET

