



INSTRUCTION

- Disconnect the power source.
- Unscrew the handle (A) and lower the canopy (B). (FIG.1)
- Fix the bracket (C) with screw (D) and dowels (E) on the ceiling. (FIG.1)
- Adjust the length of the steel cable acting on regulating terminal security (G), push the part (B) of the gripper so that the steel cable runs. (FIG.1)
- Connect the network cables to terminal (F) according to the polarity, and close the box. (FIG.1)
- Version Dimmable connect the cables inside the box (V) matching the polarity, and close the box (Fig. 1B).
- DIAGRAM OF CONNECTIONS see attached sheet
- Tense the power cable paying attention to the regulation , it dosen't have to be too tensed.
- Place the canopy in the ceiling. Screw with care the particular (A), the block cable (G).(FIG.2)
- Screw in the safety dowel (K) (Fig. 2).

- **COTTON VERSION:** Position the lower closing plex (N) inserting it inside the lampshade (L), pass the threaded tube (M) inside the hole of the closing plex (N), then rest by falling to the edge inside the lampshade itself, screw the part (O) and the washer (P) to the threaded pipe (M) (Fig. 3 + 3A).

- **PLISSÈ VERSION:** Insert the details (R) in the holes of the closing plex (N) and screw the nuts (S), then screw the hooks (T) to the detail (R)

- Pass the threaded tube (M) inside the hole of the closing plex (N) and hook the hooks (T) to the structure (Q) of the lampshade. Screw the part (O) and the washer (P) to the threaded pipe (M).

- Screw the safety dowel (V) of the part (O) (Fig. 4 + 4A).

ATTENTION:

The products of our production are suitable for the using in usual surroundings with standard temperature and humidity levels. All the operations have to be done by a technician.

CLEANING:

Switch off the power or pull the plug out.

For the periodical cleaning of the lamp use always gloves and a soft cloth (for glossy surfaces) or a feather duster for the lampshade in fabric or pleated fabric. Don't use aggressive solvents or alcohol.

Avoid absolutely to fold parts which are not expected for folding, in this case welded parts are going to be damaged.