


SHEET



CUTOUT HOLES



ELECTRICAL WIRING DIAGRAMS



Е

*Turn counterclockwise to reduce the light angle.